



## =====

## SECTION V: HEALTH HAZARD DATA

## Effects of Overexposure

EYE Contact: Liquid is minimally irritating to the eyes. High vapor concentrations may cause irritation.

SKIN CONTACT: Liquid is slightly irritating to the skin. Prolonged or repeated contact can result in defatting and drying of the skin which may result in skin irritation and dermatitis.

INHALATION: Vapors may be irritating to nose, throat and respiratory tract. High vapor concentrations may cause CNS depression.

## Medical Conditions Prone to Aggravation by Exposure

Pre-existing eye, skin and respiratory disorders may be aggravated by exposure to this product.

## Primary Routes of Entry into the Body, and Effects

Eyes, Skin, Lungs

## EMERGENCY FIRST-AID PROCEDURES

EYE CONTACT: Flush eyes with plenty of water for 15 minutes while holding eyelids open. Get medical attention.

Skin Contact: Remove contaminated clothing/shoes. Flush skin with water. Follow by washing with soap and water. If irritation occurs, get medical attention. Do not reuse clothing until cleaned.

Inhalation: Remove victim to fresh air and provide oxygen if breathing is difficult. Give artificial respiration if not breathing. Get medical attention.

INGESTION: Do not induce vomiting. If vomiting occurs spontaneously, keep head below hips to prevent aspiration of liquid into the lungs. Get medical attention.

NOTE TO PHYSICIANS: if more than 2.0 ml per kg has been ingested and vomiting has not occurred, emesis should be induced with supervision. Keep victim's head below hips to prevent aspiration. If symptoms such as loss of gag reflex, convulsions or unconsciousness occur before emesis, gastric lavage using a cuffed endotracheal tube should be considered.

## -----

## SECTION VI: REACTIVITY DATA

Stability: STABLE Hazardous Polymerization WILL NOT OCCUR.

## Hazardous Decomposition Products

Carbon Monoxide and unidentified organic compounds may be formed during combustion.

Conditions to Avoid: Avoid heat, flame and contact with strong oxidizing agents.

## Incompatibilities (Materials to Avoid)

Strong oxidizing agents.

## -----

## SECTION VII: SPILL OR LEAK PROCEDURES; WASTE DISPOSAL

## Steps to be taken if Material is Leaked or Spilled

CAUTION: combustible.\*\*\*Large Spills\*\*\* Eliminate potential sources of ignition. Wear appropriate respirator and other protective clothing. Shut off source of leak only if safe to do so. Dike and contain. Remove with vacuum trucks or pump to storage/salvage vessels. Soak up residue with an absorbent such as clay, sand or other suitable material. Place in non-leaking containers and seal tightly for proper disposal. Flush area with water to remove trace residue. Dispose of flush solution as above.

\*\*\*Small Spills\*\*\* Take up with an absorbent material and place in non-leaking containers for proper disposal.

## Waste Disposal Methods

Under EPA - RCRA (40 CFR 261.21) if this product becomes a waste material it would be an ignitable hazardous waste (D001) Refer to latest EPA or state regulations regarding proper disposal.

SECTION VIII: SAFE HANDLING AND USE INFORMATION

Respiratory Protection

Avoid prolonged or repeated breathing of vapors. If exposure may or does exceed occupational exposure limits use a NIOSH-approved respirator to prevent overexposure. In accord with 29CFR 1910.134 use either an atmosphere-supplying respirator or an air-purifying respirator for organic vapors.

Ventilation

Provide sufficient mechanical (general, or local exhaust) ventilation to maintain exposure below TLV(S)

Protective Gloves: Avoid contact with skin. Wear chemical-resistant gloves.

Eye Protection: Avoid contact with eyes. Wear safety glasses or goggles.

Other Protective Equipment: Wear chemical resistant clothing.

Hygienic Practices

WASH WITH SOAP AND WATER BEFORE EATING, DRINKING SMOKING, APPLYING COSMETICS, OR USING TOILET FACILITIES.

LAUNDER CONTAMINATED CLOTHING BEFORE REUSE. AIR-DRY CONTAMINATED CLOTHING IN A WELL VENTILATED AREA BEFORE LAUNDERING.

SECTION IX: SPECIAL PRECAUTIONS

Handling and Storing

STORE IN A COOL, DRY AREA AWAY FROM HEAT, SPARKS AND FLAME. CONTAINERS EVEN THOSE THAT HAVE BEEN EMPTIED, CAN CONTAIN EXPLOSIVE VAPORS. DO NOT CUT, DRILL, GRIND, WELD OR PERFORM SIMILAR OPERATIONS ON OR NEAR CONTAINERS TO EMPTY THEM. STATIC ELECTRICITY MAY ACCUMULATE AND CREATE A FIRE HAZARD GROUND FIXED EQUIPMENT. BOND AND GROUND TRANSFER CONTAINERS AND EQUIPMENT.

Other Precautions

WASH WITH SOAP AND WATER BEFORE EATING, DRINKING, SMOKING, APPLYING COSMETICS, OR USING TOILET FACILITIES. LAUNDER CONTAMINATED CLOTHING BEFORE REUSE. AIR-DRY CONTAMINATED CLOTHING IN A WELL VENTILATED AREA BEFORE LAUNDERING.

NATIONAL STOCK NUMBERS (NSN):

8010-00-071-4969	8010-00-298-2295	8010-00-584-3331	8010-00-616-7500	8010-01-368-7789
8010-00-078-6070	8010-00-298-2296	8010-00-584-3332	8010-00-616-7816	8010-01-380-0314
8010-00-117-8442	8010-00-298-2298	8010-00-597-7844	8010-00-664-4761	8010-01-380-0330
8010-00-117-9598	8010-00-298-2300	8010-00-597-7848	8010-00-664-7074	8010-01-380-0332
8010-00-200-8810	8010-00-298-2302	8010-00-597-7868	8010-00-664-7083	8010-01-380-0341
8010-00-285-3544	8010-00-298-2304	8010-00-597-8229	8010-00-680-0203	8010-01-380-0349
8010-00-286-7725	8010-00-515-1596	8010-00-598-2634	8010-00-687-4031	8010-01-380-0357
8010-00-286-7731	8010-00-526-1607	8010-00-598-5215	8010-00-733-2196	8010-01-380-0367
8010-00-286-7737	8010-00-526-1608	8010-00-598-5218	8010-00-753-4549	8010-01-380-0374
8010-00-286-7748	8010-00-526-2856	8010-00-598-5219	8010-00-779-9598	8010-01-396-6775
8010-00-286-7749	8010-00-527-2045	8010-00-598-5470	8010-00-853-1859	8010-01-396-6776
8010-00-286-7758	8010-00-527-2050	8010-00-598-5926	8010-00-889-7345	8010-01-418-5406
8010-00-286-9088	8010-00-527-2053	8010-00-598-5927	8010-00-965-7273	8010-01-418-5407
8010-00-290-4054	8010-00-527-3198	8010-00-598-5929	8010-01-036-6344	8010-01-418-5408
8010-00-297-2005	8010-00-527-3199	8010-00-598-5932	8010-01-040-3758	8010-01-418-5409
8010-00-297-2010	8010-00-527-3200	8010-00-598-5945	8010-01-040-3759	8010-01-418-5411
8010-00-297-2092	8010-00-530-5559	8010-00-598-7211	8010-01-040-3763	8010-01-418-5447
8010-00-297-2093	8010-00-530-5563	8010-00-598-7212	8010-01-045-7161	8010-01-418-5449
8010-00-298-2190	8010-00-577-4225	8010-00-616-7486	8010-01-115-2195	8010-01-418-5450
8010-00-298-2191	8010-00-582-1513	8010-00-616-7487	8010-01-295-0645	8010-01-418-5451
8010-00-298-2192	8010-00-582-4667	8010-00-616-7488	8010-01-324-5087	8010-01-423-3636
8010-00-298-2287	8010-00-584-3077	8010-00-616-7492	8010-01-368-7782	
8010-00-298-2292	8010-00-584-3078	8010-00-616-7495	8010-01-368-7783	
8010-00-298-2293	8010-00-584-3081	8010-00-616-7496	8010-01-368-7786	
8010-00-298-2294	8010-00-584-3329	8010-00-616-7497	8010-01-368-7788	

END OF MSDS